City Hall: 218-692-2688 Planning & Zoning: 218-692-2689 Fax: 218-692-2687



13888 Daggett Bay Rd Crosslake, Minnesota 56442 www.cityofcrosslake.org

CITY OF CROSSLAKE

PLANNING COMMISSION/BOARD OF ADJUSTMENT July 26, 2024 9:00 A.M.

Crosslake City Hall 13888 Daggett Bay Rd, Crosslake MN 56442 (218) 692-2689

PUBLIC HEARING NOTICE

Applicant: Douglas & Emily Maser

Authorized Agent: Ryan's Custom Carpentry

Site Location: 17067 Greer Lake Rd, Crosby, MN 56441 on Greer Lake - RD

Variance for:

- Lake setback of 62 feet where 100 feet is required to proposed dwelling
- Lake setback of 80 feet where 100 feet is required to proposed septic tank

To construct:

- 1,176 square foot dwelling
- Add a tank to the existing septic system

Notification: Pursuant to Minnesota Statutes Chapter 462, and the City of Crosslake Zoning Ordinance, you are hereby notified of a public hearing before the City of Crosslake Planning Commission/Board of Adjustment. Property owners have been notified according to MN State Statute 462 & published in the local newspaper. Please share this notice with any of your neighbors who may not have been notified by mail.

Information: Copies of the application and all maps, diagrams or documents are available at Crosslake City Hall or by contacting the Crosslake Planning & Zoning staff at 218-692-2689. Please submit your comments in writing including your name and mailing address to Crosslake City Hall or (crosslakepz@cityofcrosslake.org).

STAFF REPORT



Property Owner/Applicant: Douglas & Emily Maser

Parcel Number(s): 14360502

Application Submitted: June 10, 2024

Action Deadline: August 8, 2024

City 60 Day Extension Letter sent / Deadline: NA / NA

Applicant Extension Received / Request: NA / NA

City Council Date: NA

Authorized Agent: Ryan's Custom Carpentry

Variance for:

- Lake setback of 62 feet where 100 feet is required to proposed dwelling
- Lake setback of 80 feet where 100 feet is required to proposed septic tank

To construct:

- 1,176 square foot dwelling
- Add a tank to the existing septic system

Current Zoning: Shoreland District

Existing Impervious Coverage:	Proposed Impervious Coverag
12.2%	18.9%

age:

18.9%

- A stormwater management plan was submitted
- Septic design was submitted dated 3-8-2024

Parcel History:

- Greer Lake Homesites established in 1988
- September 2004 Install a new septic system

Agencies Notified and Responses Received:

County Highway Dept: N/A DNR: No comment received before packet cutoff date City Engineer: N/A Lake Association: No comment received before packet cutoff date Crosslake Public Works: No comment received before packet cutoff date Crosslake Park, Recreation & Library: N/A Concerned Parties: No comment received before packet cutoff date

POSSIBLE MOTION:

To approve/table/deny the variance to allow:

• Lake setback of 62 feet where 100 feet is required to proposed dwelling


Lake setback of 80 feet where 100 feet is required to proposed septic tank •

To construct:


- 1,176 square foot dwelling •

• Add a tank to the existing septic system As shown on the certificate of survey dated 6-26-2024





30206 Rasmussen Road Suite I P. O. Box 874 Pequot Lakes, MN 56472 218-568-4940 www.stonemarksurvey.com	L'AL CALLAR	I HEREBY CERTIFY THAT THIS SURVEY, PLAN, SPECIFICATION, OR REPORT WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION AND THAT I AM A DULY LICENSED PROFESSIONAL ENGINEER OR LAND SURVEYOR UNDER THE LAWS OF THE STATE OF MINUESOTA. CYNTHIAM. HIDDE PLS#44881 CYNTHIAM. HIDDE PLS#44881 CYNTHIAM. HIDDE PLS#44881 CYNTHIAM. HIDDE PLS#44881 CYNTHIAM. HIDDE PLS#44881 CYNTHIAM. HIDDE PLS#44881	Kevisions per City comments CMH Revisions per City comments CMH		28 AEKT NONE HOKZ I = 50 255-505¢ DVLE:	BOOK 4/3 bC. 5 FILE NAME: 24012.DWG 74012.DWG	CWH DKVMN BX: bVL CHECKED CWH LWI LWI LWI LWI CWH	GERTIFICATE OF SURVEY Doug & Emily Maser Doug & Emily Maser	1 OF
Cut & Fill estimate: Cut: 377 yards	Fill: Reuse cut where needed		DEGEND DENOTES EXISTING RETAINING WALL WALL DENOTES EXISTING RETAINING WALL DENOTES EXISTING RETAINING MALL DENOTES EXISTING RETAINING MALL DENOTES EXISTING RETAINING DENOTES EDGE OF EXISTING DENOTES EXISTING INDEX DENOTES EXISTING INDEX	1234.5 DENOTES SPOT ELEVATION (EXISTING GRADE) DENOTES EXISTING UTILITY POLE W/ GUY WIRE DENOTES EXISTING WHIT		 Y DENOTES "TO BE REMOVED" I DENOTES "TO BE REMOVED" 	 DENOTES MONUMENT FOUND DENOTES IRON MONUMENT DENOTES IRON MONUMENT O SET MARKED BY LICENSE No. 44881 ORIENTATION OF THIS BEARING SYSTEM IS BASED ON GREER LAKE HOMESITES ACCORDING TO THE RECORDED PLAT THEREOF. 	 NOTES: I. Contour interval as shown = 2 foot. Based on NGVD 29 datum. Contours shown have been obtained using standard survey topographic methodologies. Field located on 1-26-2024. Zoning for subject tract = "Shoreland District". Parcel ID of subject parcel: 14360502. The E911 address of subject parcel: 17067 Greer Lake Rd. Setbacks as shown can be subject to interpretation. Verification of setbacks by the governing body is advised prior to building. Property is in "Zone X" and "Zone A" as per the FIRM, Flood Insurance Rate Map. "Zone A" definition: Areas of 100-year flood base elevations and flood hazard factors not determined. "Zone X" activity prepared by Martin Joyce, Martin Joyce Septic Services, LLC Stonemark Land Surveying, Inc. has made no investigation or independent search for easements of record, encumbrances, restrictive covenants, ownership title evidence, or any other facts that an accurate and current title search may disclose. No wetlands were found on 5-31-2024 at the site per Ben Meister, Meister Environmental, LLC. MNC Critified Wetland Delineator #1031. 	
		GREER	KE POAD N 28° 33'00" W 66.13 N 28° 33'00" W 66.13	080			ŭ		,017 12.1% ,017 18.8%



TOP SURFACE AREA = 218 SQ. FT. BOTTOM SURFACE AREA = 65 SQ. FT. 1' DEEP WITH 3:1 SIDE SLOPES TOTAL RUN OFF STORAGE PROPOSED = 142 CU. FT. 242 CU. FT. RUN OFF AREA 1 TOP SURFACE AREA = 326 SQ. FT. BOTTOM SURFACE AREA = 157 SQ. FT. 1' DEEP WITH 3:1 SIDE SLOPES TOTAL RUN OFF STORAGE PROPOSED = RUN OFF AREA 2

Concrete 168 24,017	iveway 1,725 24,017	2,939 24,017	IMPERVIOUS CALCULATIONS	IMPERVIOUS Net Area AREA (sq.ft.)	Porch 1,152 24,017	Shed 35 24,017	Building 1 274 24,017	oncrete 145 24,017	iveway 2,907 24,017	4,513 24,017
Ŏ	Gravel Driveway	Total	IMPEF	PROPOSED	Proposed Cabin with Porch		Bui	Proposed Concrete	Existing & Proposed Driveway	Total

under the driveway through a drain pij 1) Gutters on north side drain into area 2) Gutters on south side drain into area Driveway sloped to drain into area 1 rainage: $\widehat{\mathbf{c}}$



RECREATIONAL DEVELOPMENT CLASSIFICATION LAKE ELEVATION = 1204.04 ON 1-26-2024

ORDINARY HIGH WATER ELEVATION = 1204.6

- BFE: 1207,12

6.0

<u>BENCHMARK:</u> Found 2021. Horizontal 3/8"x8" spike in N-NE root of a 1.2' red oak, 8' North of the north corner of fish cleaning house on South side of parking area and 39' West of centerline of entrance road to parking area for Public Access, 17447 Greer Lake Rd, Crosby. There is an 8" white oak 2' NW of BM tree. ELEVATION 1207.17 Information obtained from MN DNR.

OHW AS LOCATED ON 1-26-2024

BASED ON NGVD 29 DATUM

40


20


0

1

SCALE IN FEET ON 22" X 34" SHEET

30206 Rasmussen Road Suite 1 P. O. Box 874 Pequot Lakes, MN 56472 218-568-4940 Www.stonemarksurvey.com	HEREBY CERTIFY THAT THIS SURVEY, PLAN, SPECIFICATION, OR AND THAT I AM A DULY LICENSED PROFESSIONAL ENGINEER OR LAND CYNTHIAM ANDER THE LAWS OF THE STATE OF MINNESOTA. CYNTHIAM, HIDDE PLS#44881	Kevisions per City comments CMH	BOOK 4J3 6C 28 ELEED BOOK: ELEED BOOK: 54015 54015 54015	CMH DRAWN BY: PAT CMH CMH CMH PAT CMH PAT CMH CMH PAT PAT PAT PAT PAT PAT PAT PAT PAT PAT	CERTIFICATE OF SURVEY Poug & Emily Maser 21389 Goldenrod Lane Rogers, MN 55374
		LEGEND PLOTES EXISTING RETAINING WALL WALL DENOTES EXISTING RETAINING WALL DENOTES EDGE OF EXISTING MALL DENOTES EDGE OF EXISTING MALL DENOTES EDGE OF PROPOSED DENOTES EDGE OF PROPOSED DENOTES EDGE OF EXISTING DENOTES EDGE OF EXISTING DENOTES EDGE OF EXISTING DENOTES EDGE OF EXISTING DENOTES EXISTING DENOTES EXISTING INDEX	$\begin{array}{c} \bullet \\ \hline \bullet \\ \hline \bullet \\ \bullet \\ \hline \hline \hline \hline$	 DENOTES MONUMENT FOUND DENOTES IRON MONUMENT DENOTES IRON MONUMENT SET MARKED BY LICENSE No. 44881 No. 44881 ORIENTATION OF THIS BEARING SYSTEM IS BASED ON GREER LAKE HOMESITES ACCORDING TO THE RECORDED PLAT THEREOF. 	 OTES: Contour interval as shown = 2 foot. Based on NGVD 29 datum. Contours shown have been obtained using standard survey topographic methodologies. Field located on 1-26-2024. Coning for subject tract = "Shoreland District". Parcel ID of subject parcel: 14360502. The E911 address of subject parcel: 17067 Greer Lake Rd. Setbacks as shown can be subject to interpretation. Verification of setbacks by the governing body is advised prior to building. Property is in "Zone X" advised prior to building. Approximate location of septic system per kletch prepared by Martin Joyce, Martin Joyce Septic Services, LLC Stommark Land Surveying, Inc. has made no investigation or independent search for easements of record, encumbrances, restrictive covenants, ownership title evidence, or any other facts that an accurate and current title search may disclose. No wetlands were fund on a bisclose. No wetlands were found on 51-2024 at the site per Ben Meister, Meister Environmental, LLC. No easement of record has been provided for Greer Lake Road. Additional title research and/or legal advice is recommended to determine the road right-of-way. For the purposes of this survey we show the physical roadway in relation to the subject.
		AVEROAD N28°33'00' W 66.13			Percent Impervious (sq.ft) NOTES: 2.8% 0.4% 2.8% 0.4% 1.1% 0.4% 7.2% 3. Parcel ID of subject tract = "Shore 1.1% 0.7% 5. Setbacks as shown can be subject parcel 7.2% 12.2% 6. Property is in "Zone X" and "Zon A" definition: Areas of 100-year determined. "Zone A" and "Zon A" definition: Areas of 100-year determined."Zone A" and "Zon A" definition transport of the physical routway in physt





ςΩ

6.0

BENCHMARK: Found 2021. Horizontal 3/8"x8" spike in N-NE root of a 1.2' red oak, 8' North of the north corner of fish cleaning house on South side of parking area and 39' West of centerline of entrance road to parking area for Public Access, 17447 Greer Lake Rd, Crosby. There is an 8" white oak 2' NW of BM tree. ELEVATION 1207.17 Information obtained from MN DNR.

OHW AS LOCATED ON 1-26-2024

Cad 6/27/2024 11:24 AM - F:\Drawings/2024/24012 Maser/C24012.dwg

4 r


20


0

20

 Ξ

SCALE IN FEET ON 22" X 34" SHEET








NOTE: ALL DIMENSIONS ARE TO FACE OF STUD UNLESS OTHERWISE NOTED. 2 - 2" × 10" HEADERS OVER ALL EXTERIOR OPENINGS UNLESS OTHERWISE NOTED. 2 - 2" × 10" HEADERS OVER ALL EXTERIOR OPENINGS UNLESS OTHERWISE NOTED. POUBLE TRIMMERS ON OPENINGS WIDER THAN 5 FET. EXTERIOR DOORS BY THERMA-TRU OR EQUAL. WINDOWS ARE MARVIN ELEVATE, WITH ALL FROTECTION REQUIREMENTS. VERIFY ALL SIZES AND ROUGH OPENINGS WITH OWNER AND MANUFACTURER. ANY WINDOW WITHIN 18" OF THE FLOOR 16 TO BE TO BE 6'-3 1/8" UNLESS NOTED. VERIFY EXTERIOR DOOR ROUGH OPENING HEIGHT TO BE 6'-3 1/8" UNLESS NOTED. VERIFY EXTERIOR DOOR ROUGH OPENING HEIGHT

VERIFY ALL TRUSSES, BEAMS AND MICROLAMS WITH TRUSS MANUFACTURER. INSULATE AROUND ALL BATHROOMS AND BEDROOMS.

MEETING OF ENERGY CODE REQUIREMENTS TO BE THE RESPONSIBILITY OF CONTRACTOR. THIS PLAN WAS DESIGNED TO COMPLY WITH 2020 MN STATE BUILDING CODE AT THE TIME, AND FOR THE LOCATION THEY WERE DRAWN. CHECK WITH YOUR CONTRACTOR REGARDING LOCAL CODES THAT MAY VARY. THE OWNER AND CONTRACTOR ASSUME THE RESPONSIBILITY TO COMPLY WITH LOCAL CODES.








NOTE: ALL DIMENSIONS ARE TO FACE OF STUD UNLESS OTHERWISE NOTED. 2 - 2" × 10" HEADERS OVER ALL EXTERIOR OPENINGS UNLESS OTHERWISE NOTED. 2 - 2" × 10" HEADERS OVER ALL EXTERIOR OPENINGS UNLESS OTHERWISE NOTED. THAN 5 FET. EXTERIOR DOORS BY THERMA-TRU OR MITH ALL FALL PROTECTION REQUIREMENTS. VERIEY ALL SIZES AND ROUGH OPENINGS WITH OWNER AND MANUFACTURER. ANY WI

1/4"=1'-


SCALE:


VERIFY ALL TRUSSES, BEAMS AND MICROLAMS WITH TRUSS MANUFACTURER. INSULATE AROUND ALL BATHROOMS AND BEDROOMS.

MEETING OF ENERGY CODE REQUIREMENTS TO BE THE RESPONSIBILITY OF CONTRACTOR. THIS PLAN WAS DESIGNED TO COMPLY WITH 2020 MN STATE BUILDING CODE AT THE TIME, AND FOR THE LOCATION THEY WERE DRAWN. CHECK WITH YOUR CONTRACTOR REGARDING LOCAL CODES THAT MAY VARY. THE OWNER AND CONTRACTOR ASSUME THE RESPONSIBILITY TO COMPLY WITH LOCAL CODES.



REVISED MAY 24, 2024





Crow Wing County Trench/Pressure Bed Design

Property Owner: Doug & Emily Mase	er	Date: 3/8/2024
Mailing Address: 21389 Goldenrod L	ane	
City: Rogers	State: MN	Zip: 55372
Home Phone Number:	Cell: 65	1-283-0989
Site Address: 17067 Greeer Lake Rd		
City: Crosby	State: MN	Zip: 56441
Driving directions if no address issue	d:	

Legal Description: Lot 16 Block 1 Greer Lake Homesites

Sec: 36	Twp: 137	Range: 27	Twp Name: City of Crosslak
Parcel Number	: 14360502		
Lake/ River: G	reer Lake		Lake/River Classification: RD

Flow Data	Estimated Flow in Gallons per Day (GPD)				
Number of Bedrooms: 2	Bedrooms	Class I	Class II	Class III	
Dwelling Classification: I	2	300	225	180	
0	3	450	300	218	
System Type: I	4	600	375	256	
GPD: 300	5	750	450	294	
	6	900	525	332	
Wells	7	1050	600	370	
Deep Well: Existing Deep	8	1200	675	408	

Deep Well: Existing Deep Shallow Well: None Wells to be sealed (if applicable)?

Setbacks

Tank(s) to: Well +50 House +10 Property Line +10

<u>Drainfield</u> to: Well +50
House +20
Property Line +10

Sewer Line to well: +50 Air Test: No

* NEED Variance for the proposed tank = 10' Instead of 100' # Additional System Notes and Information: NEW CONSTRUCTION - Removing ADDING A SEPTIC TANK PRIOR TO THE EXISTING TANK. the existing Cabin License Number: 2129 Designer Name: Martin Joyce Address: City: State: Zip:

Home Phone Number:

Cell: 218-820-2621

E-Mail Address: joycem@brainerd.net

I hereby certify that I have completed this work in accordance with all applicable requirements.


Designer Signature: _	Mart Jon	Date: 3/8/2024

Page 1 of 9

	Crow	Wing Coun	ty Trench/	Pressu	re Bed D	esign		
Propert			-				gner's Initial	s:
	Pro	posed	Date: 3/8/202 (000 Gzl	4-	Exis	t 1007) Val.	
	Tank Sizing -							
Α.	Septic Tank Capacity: 1500 (Gallons -> l	will be	Zoov	Val 1	Ser	otic Tank Capa	
	Tank Type: 2 Compartments	ſ∕⁄ Fil	ter: Yes	701	tal	Bedrooms	Minimum	GD/E
	Garbage Disposal/Basement	Lift Station: N	o Disposal or I	Lift		5 or less	2,000	<u>2,25</u> 3,00
B.	Pump Tank Canacity: 500 Ga	llons (7080.2)	00)			6 or 7 8 or 9	2,000	3,75
	a. Alarm Type: Electric	N E.	ict.					
	a. Alarm Type: Electric Soils Depth to Restricting Layer: 5	$\backslash \rho$	isling					
C	Depth to Restricting Layer: 5	fropose	0					
	Native SSF:.83	11.						
D.								
	(Perc. Rate [Optional]	MPI)						
Ente	er GPD next to the type of s	ystem						
	Rock Trenches		•					
E.	6 in. Trench Depth	$GPD \times D =$	0.0sq. ft.		Cubic `	Yards of Ro	ck: 0 yds³	
F.	12 in. Trench Depth	$GPD \times D \times$.8 = 0.0sq. ft.		Cubic `	Yards of Ro	ck: 0 yds³	
G.	18 in. Trench Depth	GPD × D ×	.66 = 0.0sq. ft.		Cubic T	Yards of Ro	ck: 0 yds³	
H.	24 in. Trench Depth	GPD × D ×	.6 = 0.0sq. ft.		Cubic	Yards of Ro	ck: 0 yds³	
I.	Divide (E-H) by Trench Wid		-				·	
	Chamber Trenches							
-							0	~
J.	Brand:				ne chamber	(L x W):	ft. ×	ft.
	6-11 in. Chamber Depth		$D \times D = 0.0$ sq.					
	12 in. Chamber Depth		$D \times D \times .8 = 0.1$	0sq. ft.				
М.	Select from (K-L) if installing	g Chamber Tro	enches: 0.0					
N.	Divide (M) by Trench Width	for lineal feet	$0.0 \div 0 =$	Linea	al Feet			
О.	Total Chambers Needed (Ro	und Up):	Chambers					
	Seepage/Pressure Bed	ls						
P.	Seepage Bed GPD	\times D \times 1.5 = 0.0	Osq. ft.					
	a. Bed Dimensions	ft, ×	ft.					
	b. <u>Cubic Yards of Rock</u>		th × Bed Width	× Rock	Depth f	$t. \div 27 = 0 v$	ds ³	
0	Pressure Bed 300 GPD × I	-			-	, vj		
<u>ب</u>	a. <u>Bed Dimensions</u>	9ft x 20ft	- Ex	1511	~ G			
		· · · · · · · · · · · · · · · · · · ·						

Bed Length × Bed Width × Rock Depth 1ft. \div 27 = 9 yds³ b. Cubic Yards of Rock

Additional System Notes and Information: USE THE EXISTING SEPTIC/LIFT TANK AND PRESSURE BED DRAINFIELD. NEED TO ADD A SEPTIC TANK TO BRING UP TO CODE SIZING WISE. USE THE EXISTING PUMP. SUGGEST REPAIRING THE ALARM IN THE LIFT.



Page 2 of 9

Å.



wq-wwists4-31b

4/28/2021

Compliance inspection report form

520 Lafayette Road North St. Paul, MN 55155-4194 Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

Instructions: Inspector must submit completed form to Local Governmental Unit (LGU) and system owner within 15 days of final determination of compliance or noncompliance. Instructions for filling out this form ar located on the Minnesota Pollution Control Agency (MPCA) website at <u>https://www.pca.state.mn.us/sites/default/files/wq-wwists4-31a.pdf.</u>

Inspector must submit completed form to Local Governmental Unit (LGU) and system owner within 15 days of final

determination of complian	nce or noncompliance.		l tracking p	urposes	:	
			rosslake	. 197	Da	27
Property Information	Dn Local tracking nu	Sec	36 Tw	o 137	Rg	21
Parcel ID # or Sec/Twp/Rar			permit			
Local regulatory authority in						
Property address:	17067 Greer Lake Rd, Crosby, MN 56441					
Owner/representative:	Doug & Emily Maser Owner's phon	e: 651-283	-0989			
Brief system description:						·····
	Gravity from the cabin to a Sather combo septic/lift tank. Manhole covers are at th Pumps to a pressure bed drainfield. Rock bed is 9' x 29' per the install records. 2" bed.					
System Status						
System Status on date (mm	n/dd/yyy): <u>3/8/2024</u>					
Compliant - C	Certificate of compliance* 🛛 Noncompliant - Notic	ce of nor	icomplia	nce		
(Valid for 3 year	rs from report date unless evidence of an		-			
	o public health or safety requiring removal Systems failing to protect g	round wate	er must be	upgrade	d, repla	aced,
	nder section 145A.04, subdivision 8 is or use discontinued within	the time rec	quired by lo	cal ordin	nance.	
discovered or a s Ordinance.)	shorter time frame exists in Local An imminent threat to publi	ic health an	d safety /ľ	(PHS) n	ust he	
,	upgraded, replaced or its w					
	system status date above and does not receipt of this notice or with	hin a shorte	r period if i	required		
guarantee future		145A.04 si	ubdivision	3.		
Reason(s) for no	oncompliance (check all applicable)					
	iblic Health (Compliance Component #1) - Imminent threat to public health and safe	tv				
	y (Compliance Component #2) - Failing to protect groundwater					
	iance Conditions (Compliance Component #3) - Imminent threat to public health and	d safetv				
A	iance Conditions (Compliance Component #3) - Failing to protect groundwater	,				
	bandoned according to Minn. R. 7080.2500 (Compliance component #3) - Failing to	protect are	oundwater			
	on (Compliance Component #5) - Failing to protect groundwater					
	rmit/monitoring plan requirements (Compliance Component #4) - Noncompliant - loc	cal ordinand	ce applies			
Comments or recom						
Permit #B2004353						
o						
Certification						
I hereby certify that all the n	ecessary information has been gathered to determine the compliance status of this	system. N	0			
possible abuse of the system	em performance has been nor can be made due to unknown conditions during syste m, inadequate maintenance, or future water usage.	em construc	ction,			
By typing my name below can be used for the purpose	r, I certify the above statements to be true and correct, to the best of my knowledge, a of processing this form.	, and that th	nis informa	ion		
Business name:	Martin Joyce Septic Service, Inc. Certification number	er: 5453				
Inspector signature:	Martin Joyce License numbe	er: 2129				
	(This document has been electronically signed) Phone number	er: 218-820	-2621			
	y required supporting documentation (must be attached)					
	System/As-Built I Locally required forms Tank Integrity As	sessment	Оре	erating P	ermit	
Other information (list)):					
https://www.pca.state.mn.us	651-296-6300 800-657-3864 Use your preferred relay services	Available in a	alternative fo	mats		

Page 3 of 9

Property address:	17067 Greer Lake Rd, Crosby, MN 56441		
Business Name:	Martin Joyce Septic Service, Inc.	Date:	3/12/2024
	Aller and a start start and a start		

1. Impact on Public Health - Compliance component #1 of 5

Compliance criteria:		Attached supporting documentation:
System discharges sewage to the ground surface.	☐ Yes* ☑ No	Other: Not Applicable
System discharges sewage to drain tile or surface waters.	🗌 Yes* 🗹 No	
System causes sewage backup into dwelling or establishment.	□ Yes* ☑ No	
Any "yes" answer above indicates	the system is	

an Imminent Threat to Public Health and Safety.

Describe verification methods and results:

Seasonally used. There was no water use at the cabin at the time of inspection.

2. Tank Integrity - Compliance component #2 of 5

Compliance criteria:			Atta	ched supporting document	ation:		
System consists of a seepage pit, cesspool, drywell, or leaching pit, or other pit?	☐ Yes* 🗹	No	1	Empty tank(s) viewed by ins Name of maintenance busin	•	Al's Sewer	
F				License number of maintena	ance busine	ess:	L318
Sewage tank(s) leak below their	☐ Yes* 🗹	No		Date of maintenance:			3/8/2024
designed operating depth.				Existing tank integrity asses	sment (Atta	ach)	
				Date of maintenance (mm/dd/yyy):	•	within three	
If yes, which sewage tank(s) leaks:			(See form instructions to ensure assessmer Minn. R. 7082.0700 subp. 4 B (1))			ones with	
Any "yes" answer above indicates the system is failing to protect groundwater	:			Tank is Noncompliant (pum Other:		cessary - e	xplain below)
Describe verification methods and resul	ts:						

Video inspected the tank for cracks and baffles - OK.

https://www.pca.state.mn.us wq-wwists4-31b 1/11/21

651-296-6300 800-657-3864 Use your preferred relay services Available in alternative formats

Page 4 of 9

	Property address:	17067 Greer Lake Rd, Crosby, I					
	Business Name:	Martin Joyce Septic Service, Inc	λ.		Date:	3/12/2024	
3.	Other Complian	e Conditions - Complia	nce component #3 c	of 5			
	3a. Maintenance hole	covers appear to be structurally u	insound (damaged, cracke	d, etć.), or unsecure	d.	□ Yes* √No	hknown
	3b. Other issues (elect *Yes to 3a or 3b -		☐ Yes* ☑No	nknown			
		System is an imminent threat to ective of ground water for other of				Yes* No	
		oned in accordane with Minn. R.					
	*Yes to 3c or 3d - Sys	tem is failing to protect ground	twater.				
	Describe verification	n methods and results:					
	Attached supporting	documentation: Ot applica	ible [_]				
4.	Operating Permi	t and Nitrogen BMP * -	Compliance #4 of 5	2	Not Appli	cable	
	Is the system required BMP=Best Manag	under an Operating Permit? to employ a Nitrogen BMP specif ement Practice(s) specified in the questions is "no", this section	e system design	☐ Yes ☐ Yes pleted.	□ No □ No	lf "yes", A below If "yes", B below	-
	Compliance criteria:						
	•	Permit requirements been met?		Yes	🗌 No		
	a. Have the Operatingb. Is the required nitro	Permit requirements been met? jen BMP in place and properly fu idicates Noncompliance.	inctioning?	Yes Yes	□ No □ No		
	 a. Have the Operating b. Is the required nitro Any "no" answer in 	gen BMP in place and properly fu	inctioning?				
	 a. Have the Operating b. Is the required nitro Any "no" answer in 	gen BMP in place and properly fundicates Noncompliance.	inctioning?				
	 a. Have the Operating b. Is the required nitro Any "no" answer in 	gen BMP in place and properly fundicates Noncompliance.	inctioning?				
	 a. Have the Operating b. Is the required nitro Any "no" answer in 	gen BMP in place and properly fundicates Noncompliance.	Inctioning?				
	 a. Have the Operating b. Is the required nitro Any "no" answer in 	gen BMP in place and properly fundicates Noncompliance.	inctioning?				
	 a. Have the Operating b. Is the required nitro Any "no" answer in 	gen BMP in place and properly fundicates Noncompliance.	inctioning?				
	 a. Have the Operating b. Is the required nitro Any "no" answer in 	gen BMP in place and properly fundicates Noncompliance.	inctioning?				
	 a. Have the Operating b. Is the required nitro Any "no" answer in 	gen BMP in place and properly fundicates Noncompliance.	inctioning?				
	 a. Have the Operating b. Is the required nitro Any "no" answer in 	gen BMP in place and properly fundicates Noncompliance.	inctioning?				
	 a. Have the Operating b. Is the required nitro Any "no" answer in 	gen BMP in place and properly fundicates Noncompliance.	inctioning?				
	 a. Have the Operating b. Is the required nitro Any "no" answer in 	gen BMP in place and properly fundicates Noncompliance.	inctioning?				
	 a. Have the Operating b. Is the required nitro Any "no" answer in 	gen BMP in place and properly fu dicates Noncompliance. n methods and results:	nctioning? bermit (Attach)				

Property address:	17067 Greer Lake Rd, Cro	sby, MN 56441	·		
Business Name:	Martin Joyce Septic Servic	e, Inc.		Date: <u>3/12/2024</u>	
Soil Separation	- Compliance compor	nent #5 of 5			
Date of installation	n: <u>9/27/2004</u> (mm/dd/yyyy)	_ 🗍 Unknowr	1		
Shoreland/Wellhead pro lodging? Compliance criteria	otection/Food beverage	✓ Yes	No	Attached supporting documentation: Soil observation logs completed for Two previous verifications of require separation (<i>Attach</i>)	report (Attach)
5a.For systems built p and not located in Protection Area o beverage or lodgi Drainfield has at lo	rior to April 1, 1996, Shoreland or Wellhead r not serving a food, ng establishment: east a two-foot vertical ce from periodically	Yes	⊡No*	 Not applicable (No soil treatment an Soils also verified with a 2013 s compliance inspection. 	
5b.Non-performance s 1996, or later or fo systems located in Protection Areas o beverage, or lodgi Drainfield has a th	systems built April 1, or non-performance in Shoreland or Wellhead or serving a food, ing establishment: stree-foot vertical se from periodically	Yes	∏No*	Indicate depths of elevations A. Bottom of distribution media B. Periodically saturated soil/bedrock C. System separation D. Required compliance separation* *May be reduced up to 15 percent if allo Ordinance. 	24" 60" 36" 36" wed by Local
systems built unde Type IV or V syste Rules (7080, 2350 (Advanced Inspec Drainfield meets ti	tor License required) ne designed vertical se from periodically	Yes	<u></u> No*		

Upgrade requirements: (Minn. Stat. 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, or its use discontinued, notwithstanding any local ordinance that is mor strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establisments as defined in law.

https://www.pca.st	ate.mn.us	651-296-6300	800-657-3864	Use your preferred relay services	Available in alternative formats	
wq-wwists4-31b	4/28/2021					

Martin Joyce Septic Service, Inc.

27604 County Road 3, Merrifield, MN 56465

Septic System Management Plan

Property Owner: Doug & Emily Maser	Phone:	651-283-0989	Date:	3/8/2024

Mailing Address: 21389 Goldenrod Lane, Rogers, MN 55372

Site Address: 17067 Greer Lake Rd, Crosby, MN 56441

This management plan will identify the operation and maintenance activities necessary to ensure long-term performance of your septic system. Some of these activities must be performed by you, the homeowner. Other tasks must be performed by a licensed septic service provider.

 System Designer:
 check every ______ months

 Local Government:
 check every ______ months

 State Requirement:
 check every ______ months

My system needs to be checked every <u>36</u> months

Homeowner Management Tasks (performed monthly unless otherwise stated)

Leaks - Check (look,listen) for leaks in toilets and dripping faucets. Repair leaks promptly *Surfacing sewage* - Regularly check for wet or spongy soil around your soil treatment area. *Effluent filter - Inspect and clean twice a year or more*

Alarms - Alarm signal when there is a problem: contact Service Provider any time an alarm signals *Event counter or water meter* - Monitor your average daily water use (if it applies)

Professional Management Tasks

Check and clean the in-tank effluent filter

Check the sludge/scum layer levels in all septic tanks

Recommend if tank should be pumped

Pump all compartments of septic tank at least every 36 months

Check inlet and outlet baffles

Clean drainfield laterals (if it applies)

Check the drain field effluent levels in the rock layer

Check the pump and alarm system functions (if it applies)

Check wiring for corrosion and function (if it applies)

Check dissolved oxygen and effluent temperature in tank

Provide home owner with list of results and any action to be taken

Replacement system for this residence, a secondary site has not been identified.

" I understand it is my responsibility to properly operate and maintain the sewage treatment system on this property, utilizing the Management Plan. If requirements in this Management Plan are not met, I will promptly notify the permitting authority and take necessary corrective actions. If I have a new system, I agree to adequately protect the reserve area for future use as a soil treatment system."


Property Owner Signature:	Date:
Designer Signature:	Date:
Permitting Authority Signature:	Date:

Cell: 218-820-2621 Page 7 of 9


Soils information

from 2013

Septic Inspection



Page 8 of 9



Page 9 of 9

Variance Applica Planning and Zoning D 13888 Daggett Bay Road, Cross 218.692.2689 (Phone) 218.692.2687 (Fa	epartment slake, MN 56442	lake.org
Receipt Number: <u>کابل ا</u> 92 Property Owner(s): Douglas & Emily Maser	Permit Number:	240098V
Mailing Address: 21389 Goldenrod Lane, Roger MN Mailing Address: 17067 Greer Lake Rd, Crosby, MN 56441 Site Address: 651-283-0989 Phone Number: 651-283-0989 E-Mail Address: drmaser@gmail.com Parcel Number(s): 14360502 Legal Description: Lot 16 Block 1 Greer Lake Homesites Sec 36 Twp 137 Rge 26 27 28	(Check applie	ht-of-Way Setback back Setback Setback
Lake/River Name: Greer Lake Do you own land adjacent to this parcel(s)? Yes If yes list Parcel Number(s)	Septic Dra Imperviou	ainfield Setback us Coverage
Authorized Agent: Ryan's Custom Carpentry Agent Address: 17741 County Rd 11, Crosby, MN 56441 Agent Phone Number: 763-238-7878	□ Building I □ Patio Size	Height
Signature of Property Owner(s) Signature of Authorized Agent(s) All emplications must be accompanied by a signed Cortificate of S	Dat	
 All applications must be accompanied by a signed Certificate of S Fee \$750 for Residential and Commercial Payable to "City of Cro No decisions were made on an applicant's request at the DRT mea after DRT does not constitute approval. Approval or denial of app Planning Commission/Board of Adjustment at a public meeting as City of Crosslake Land Use Ordinance. 	sslake" eting. Submittal of a plications is determine	ned by the ute 462 and the

Lake Class_	RD	Septic:	Com
-------------	----	---------	-----

npliance nq SSTS Design 3-8-24 Installation upgrade



Practical Difficulty Statement

Pursuant to City of Crosslake Ordinance Article 8 – Variances may be granted when it is found that strict enforcement of the Land Use Ordinance will result in a "practical difficulty".

Please answer the following questions regarding the "practical difficulty" for your variance request.

- Is the Variance request in harmony with the purposed and intent of the Ordinance? Yes No
 Why:
 Defer to the Planning Commission/Board of Adjustment
- 2. Is the Variance consistent with the Comprehensive Plan?

Yes No No Why: Defer to the Planning Commission/Board of Adjustment

3. Is the property owner proposing to use the property in a reasonable manner not permitted by the Land Use Ordinance?

Yes 🖬 🛛 No 🗆

Why:

The current location of the cabin is not compliant with the lake setback. The proposal is mostly in keeping the existing footprint,

but the request is to expand it by 4 feet in width. We would also like to add a 2nd bathroom, so we will need to add a 3rd tank to the septic system.

We would like to add the 3rd tank to the existing location of the septic. Lastly, the structure will need to be reoriented slightly to avoid encroaching on the neighbor's property line.

4. Will the issuance of a Variance maintain the essential character of the locality?

Yes 🖬 🛛 No 🗆

Why:

We intend to keep the same look and location of the current cabin structure to cause minimum changes to the character of the property. The structure will maintain similar distance from the lake as all other cabins on the lake and be no closer than existing.

The addition of another septic tank won't affect the character of the property.

5. Is the need for a Variance due to circumstances unique to the property and not created by the property owner?

Yes 🔳	No 🗆
Why:	· · · · · · · · · · · · · · · · · · ·
The cabin was	built in the 1950s before the current setback ordinances were in place. Septic, drain field, and well
were all in place	e prior to us owning the property. If we were to place the structure at the 100 ft setback, we would be encroaching on the neighbor's
drainfield, our d	drainfield, and existing power poles. Trees would also need to be removed from the property, which is not ideal.

6. Does the need for a Variance involve more than economic considerations?

Yes 🔳 🛛 No 🗆

Why:

Keeping the septic where it is located and adding another tank in that location will prevent from encroaching on the compliant drain field currently in place. Building farther back would put the new structure too close to the drain field and prevent any future buildings, such as a garage, to be on the property without causing major rework of the property or removing trees. We want to cause minimal disruption to the property.



City of Crosslake Planning Commission/Board of Adjustment

FINDINGS OF FACT

SUPPORTING / DENYING A VARIANCE REQUEST

A Variance may be granted by the Planning Commission/Board of Adjustment when it is found that strict enforcement of the Land Use Ordinance will result in a "practical difficulty" according to Minnesota Statute Chapter 462. The Planning Commission/Board of Adjustment should weigh each of the following questions to determine if the applicant has established that there are "practical difficulties" in complying with regulations and standards set forth in the Land Use Ordinance.

 Is the Variance request in harmony with the purposes and intent of the Ordinance? Yes No Why:

Is the Variance consistent with the Comprehensive Plan?
 Yes No
 Why:

Is the property owner proposing to use the property in a reasonable manner not permitted by the Land Use Ordinance?
 Yes No
 Why:

 4. Will the issuance of a Variance maintain the essential character of the locality? Yes No Why:

5. Is the need for a Variance due to circumstances unique to the property and not created by the property owner?

Yes No Why?

 Does the need for a Variance involve more than economic considerations? Yes No Why: